

APPENDIX B: SUMMARY OF PCI LEVELS

TABLE B.1: PAVEMENT CONDITION INDEX SUMMARY – SECTION LEVEL

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VRB	RW 4-22	Runway	8305	437,874	84	Satisfactory
VRB	RW 4-22	Runway	8310	48,928	100	Good
VRB	RW 12L-30R	Runway	8205	169,050	84	Satisfactory
VRB	RW 12L-30R	Runway	8215	28,250	78	Satisfactory
VRB	RW 12L-30R	Runway	8220	87,500	81	Satisfactory
VRB	RW 12R-30L	Runway	8105	162,750	100	Good
VRB	RW 12R-30L	Runway	8110	573,090	100	Good
VRB	RW 12R-30L	Runway	8115	31,500	100	Good
VRB	TW A	Taxiway	101	12,340	88	Good
VRB	TW A	Taxiway	102	25,470	77	Satisfactory
VRB	TW A	Taxiway	105	59,360	64	Fair
VRB	TW A	Taxiway	110	29,000	87	Fair
VRB	TW A	Taxiway	115	5,740	57	Fair
VRB	TW A	Taxiway	120	11,778	66	Fair
VRB	TW A	Taxiway	125	11,250	61	Fair
VRB	TW A	Taxiway	130	9,282	88	Fair
VRB	TW A	Taxiway	134	9,825	83	Satisfactory



APPENDIX B: SUMMARY OF PCI LEVELS

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VRB	TW A	Taxiway	135	52,226	58	Fair
VRB	TW A	Taxiway	140	7,788	88	Good
VRB	TW A1	Taxiway	150	7,244	64	Fair
VRB	TW A1	Taxiway	155	11,073	88	Good
VRB	TW A2	Taxiway	142	13,827	84	Satisfactory
VRB	TW A2	Taxiway	143	4,288	84	Satisfactory
VRB	TW B	Taxiway	201	10,353	83	Satisfactory
VRB	TW B	Taxiway	205	73,775	59	Fair
VRB	TW B	Taxiway	206	4,213	51	Poor
VRB	TW B1	Taxiway	151	5,576	68	Fair
VRB	TW B1	Taxiway	152	8,073	88	Good
VRB	TW C	Taxiway	305	83,003	94	Good
VRB	TW C	Taxiway	306	31,809	83	Satisfactory
VRB	TW C	Taxiway	307	6,396	88	Good
VRB	TW C	Taxiway	309	10,088	84	Satisfactory
VRB	TW C	Taxiway	310	38,030	68	Fair
VRB	TW C	Taxiway	312	32,050	80	Fair
VRB	TW C	Taxiway	315	195,535	94	Good
VRB	TW C1	Taxiway	390	43,685	100	Good
VRB	TW C2	Taxiway	328	5,859	94	Good
VRB	TW C2	Taxiway	330	23,333	94	Good
VRB	TW C2	Taxiway	335	15,426	100	Good
VRB	TW C3	Taxiway	350	28,935	42	Poor
VRB	TW C3	Taxiway	354	10,620	39	Very Poor
VRB	TW C3	Taxiway	355	9,405	88	Good
VRB	TW C3	Taxiway	356	12,737	73	Satisfactory
VRB	TW C4	Taxiway	360	15,336	100	Good
VRB	TW C4	Taxiway	365	18,877	94	Good
VRB	TW C5	Taxiway	375	17,291	100	Good
VRB	TW C5	Taxiway	385	11,888	88	Good
VRB	TW C6	Taxiway	304	15,197	100	Good
VRB	TW D	Taxiway	405	25,540	100	Good
VRB	TW D	Taxiway	410	14,032	84	Fair
VRB	TW D	Taxiway	414	19,326	100	Good
VRB	TW D	Taxiway	415	57,753	81	Satisfactory
VRB	TW D	Taxiway	420	13,244	88	Good
VRB	TW E	Taxiway	505	16,516	80	Satisfactory
VRB	TW E	Taxiway	515	35,421	84	Satisfactory
VRB	TW E	Taxiway	520	182,990	94	Good
VRB	TW E1	Taxiway	525	22,920	94	Good
VRB	TW E3	Taxiway	530	29,517	100	Good
VRB	TW F	Taxiway	605	21,104	88	Good
VRB	TW F	Taxiway	610	49,875	84	Satisfactory
VRB	TW F	Taxiway	611	21,000	88	Good
VRB	TW F	Taxiway	612	30,660	82	Satisfactory
VRB	TW F	Taxiway	630	7,958	84	Satisfactory
VRB	TW F1	Taxiway	625	8,845	82	Satisfactory

Network ID	Branch ID	Branch Use	Section ID	Area (SF)	PCI	Condition Rating
VRB	TW F2	Taxiway	620	9,130	83	Satisfactory
VRB	TL AP W	Taxilane	3305	46,522	94	Good
VRB	TL SW	Taxilane	4505	35,304	86	Good
VRB	TL SW	Taxilane	4510	47,352	73	Satisfactory
VRB	TL SW	Taxilane	4515	39,359	67	Fair
VRB	TL SW	Taxilane	4520	31,196	65	Fair
VRB	TL SW	Taxilane	4525	24,241	70	Fair
VRB	TL SW	Taxilane	4530	13,852	86	Good
VRB	TL SW	Taxilane	4535	28,864	17	Serious
VRB	AP CENTER	Apron	4205	230,112	42	Poor
VRB	AP CENTER	Apron	4210	24,110	50	Poor
VRB	AP CENTER	Apron	4215	206,039	48	Poor
VRB	AP CENTER	Apron	4220	37,054	37	Very Poor
VRB	AP CENTER	Apron	4240	110,890	100	Good
VRB	AP CENTER	Apron	4245	122,479	100	Good
VRB	AP CENTER	Apron	4250	50,351	98	Good
VRB	AP CENTER	Apron	4255	201,350	100	Good
VRB	AP CENTER	Apron	4260	14,850	100	Good
VRB	AP N	Apron	4805	314,515	100	Good
VRB	AP N	Apron	5405	221,090	91	Good
VRB	AP N	Apron	5410	51,735	43	Poor
VRB	AP N	Apron	5420	11,919	90	Good
VRB	AP RU 12L	Apron	5505	22,034	59	Fair
VRB	AP RU 12L	Apron	5506	15,486	81	Satisfactory
VRB	AP RU 12R	Apron	5205	98,702	94	Good
VRB	AP RU 30L	Apron	5305	52,790	94	Good
VRB	AP RU 30R	Apron	5515	21,838	85	Satisfactory
VRB	AP RU 4	Apron	5105	26,770	58	Fair
VRB	AP RU 4	Apron	5110	35,776	84	Satisfactory
VRB	AP SW	Apron	4105	218,427	30	Very Poor
VRB	AP SW	Apron	4110	2,787	66	Fair
VRB	AP W	Apron	4305	24,038	83	Satisfactory
VRB	AP W	Apron	4310	85,647	47	Poor
VRB	AP W	Apron	4312	3,090	70	Fair
VRB	AP W	Apron	4315	31,823	85	Satisfactory
VRB	AP W	Apron	4405	205,414	46	Poor
VRB	AP W	Apron	4410	40,406	56	Fair
VRB	AP W	Apron	4415	14,800	66	Fair
VRB	AP W	Apron	4420	135,726	90	Good
VRB	AP W	Apron	4425	79,836	94	Good
VRB	AP W	Apron	4430	39,584	86	Good
VRB	AP W	Apron	4435	83,983	88	Good
VRB	AP W	Apron	4440	101,138	100	Good
VRB	AP W	Apron	4445	32,834	40	Very Poor
VRB	AP W	Apron	4450	15,826	74	Satisfactory

